

- 1) Dimension is measured at the maximum solder ball diameter, parallel to primary datum c
- 2) Primary datum c and seating plane are defined by the domed crowns of the balls All dimensions are in units mm